

ВИНТЫ

| Форма | Кат. № детали | Наличие | Размеры (мм) | | | | | | Зажимная сила (N/m) | Прим. пластины |
|---|-----------------|-----------|--------------|-------|--------|------|-------|------|---------------------|----------------|
| | | | a | øb | c | d | e | f | | |
| | ASM34S | ● | M3 | 4.8 | 8 | 5 | | 2 | - | |
| | ASM34L | ● | | | 11 | 8 | | | - | |
| | ASM54 | ● | M5x0.8 | 9 | 14 | 9 | | 3 | - | |
| | CHHM3.5-10 | ● | M3.5x0.6 | 6 | 13.5 | 10 | | 3 | 3.0 | |
| | CHHM4-10 | | M4x0.7 | 7 | 14 | | | | | |
| | CHHM5-14 | | M5x0.8 | 8.5 | 19 | 14 | 4 | 5.0 | | |
| | CHHM5-18 | ● | | | 23 | 18 | | | | |
| | CHHM6-15 | | M6 | 10 | 21 | 15 | 5 | 8.5 | | |
| | CHHM6-20 | | | | - | 20 | | | | |
| | CHHM6-25 | | | | 31 | 25 | | | | |
| <p>Винт с шестигранной шляпкой (JISB1176)</p> <p>CM***H</p> | CM3X0.5X6 | | M3x0.5 | 5.5 | 9 | 6 | 2.5 | 2.2 | | |
| | CM3X0.5X10 | | | | 13 | 10 | | | | |
| | CM4X0.7X10 | | | | M4x0.7 | 7 | | | 14 | 10 |
| | CM4X0.7X12 | | 16 | 12 | | | | | | |
| | CM4X0.7X14 | ● | 18 | 14 | | | | | | |
| | CM4X0.7X15 | | 19 | 15 | | | | | | |
| | CM4X0.7X20 | ● | 24 | 20 | | | | | | |
| | CM4X0.7X20-M0-A | ● | 6 | 24 | 20 | 4 | 5.0 | | | |
| | CM5X0.8X8 | | M5x0.8 | 8.5 | 13 | | | 8 | | |
| | CM5X0.8X10-A | ● | | | 15 | | | 10 | | |
| | CM5X0.8X12 | ● | | | 17 | | | 12 | | |
| | CM5X0.8X12-A | ● | | | 17 | | | 12 | | |
| | CM5X0.8X14 | ● | | | 18 | | | 14 | | |
| | CM5X0.8X16 | | | | 21 | | | 16 | | |
| | CM5X0.8X16-A | ● | | | 21 | | | 16 | | |
| | CM5X0.8X18 | | | | 23 | | | 18 | | |
| | CM5X0.8X20-A | ● | | | 25 | | | 20 | | |
| | CM5X0.8X25-A | ● | | | 30 | | | 25 | | |
| | CM5X15 | | | | M5 | 20 | 15 | 5 | 8.5 | |
| | CM6X1X16-A | ● | M6x1.0 | 10 | 22 | 16 | | | | |
| | CM6X1X20-A | ● | | | 26 | 20 | | | | |
| | CM6X1X25-A | ● | | | 31 | 25 | | | | |
| | CM6X1.0X40-A | ● | | | 46 | 40 | | | | |
| | CM6X10 | | M6 | 10 | 16 | 10 | | | | |
| | CM6X15 | | | | 21 | 15 | | | | |
| | CM6X16 | | | | 22 | 16 | | | | |
| | CM6X20 | | | | 26 | 20 | | | | |
| | CM6X25 | | | | 31 | 25 | | | | |
| | CM6X30-S | ● | M6x1.0 | 10 | 35.7 | 28 | 6 | 25.0 | | |
| | CM8X1.25X20-A | ● | M8x1.25 | 13 | 28 | 20 | | | | |
| | CM8X1.25X25-A | ● | | | 33 | 25 | | | | |
| | CM8X30H | ● | | | 36 | 30 | | | | |
| | CM10X30 | | M10x1.5 | 16 | 30 | 20 | 8 | 40.0 | | |
| | CM10X30H | ● | | | 16 | 38 | 30 | 6 | 40.0 | |
| CM12X30H | ● | M12x1.75 | 18 | 40 | 30 | 8 | 70.0 | | | |
| CM16X40H | ● | M16x2 | 24 | 54 | 40 | 10 | 100.0 | | | |
| C0.375X1.125H | ● | 3/8-24UNF | 14.27 | 38.11 | 28.58 | 5.55 | 35.0 | | | |
| C0.500X1.375H | ● | 1/2-20UNF | 19.05 | 47.63 | 34.93 | 7.94 | 70.0 | | | |
| SD06-A3 | ● | M10x1.5 | 16 | 70 | 60 | 8 | 40.0 | | | |
| SD08-98 | ● | M12x1.75 | 18 | 77 | 65 | 10 | 70.0 | | | |
| <p>FSHM*-H</p> | FSHM8-30 | ● | M8x1.25 | 11 | 30 | 27 | 5 | 25.0 | | |
| | FSHM8-30H | ● | | | | | | 25.0 | | |
| | FSHM10-40 | ● | M10 | 14 | 40 | 36.5 | 6 | 40.0 | | |
| | FSHM10-40H | ● | | | | | | 40.0 | | |
| | SHCM4-10 | ● | M4x0.7 | 6 | 14 | 10 | 3 | 3.0 | | |
| | SHCM4-12 | ● | | | 16 | 12 | | | | |
| | SHCM4-16 | ● | | | 20 | 16 | | | | |
| | CTS-M6 | ● | M6x1 | 10 | 25 | 16.4 | 4 | 5.0 | | |