

## Quick Change Drilling Head

## Tungaloy's System



**Others** 

## Economical

Use a short carbide head needed for the drilling operation



Expensive full carbide drill







Reduce machine downtime by replacing the head on the machine



Inefficient
















> 10 min

< 1 min

Versatile Tool range in increments of 1 mm covers from ø10 to ø19.9 mm; 10 different heads in 0.1 mm increments mount on each drill body



**x 10 =** Covers for hole diameter range from Ø10 to Ø19.9 mm