







Для черновой обработки перед прорезанием шпоночных пазов. Радиус скругления вершины: $r = 0.2 \sim 0.4 \text{ mm}$


































ap

ар = Макс. глубина резания S = Размер присоединительной резьбы

Кат. №	Сплав	Кол-во	Угол			Размер	Ключ	Крутящий			
	AH725	зубьев	спирали	øDс	ød1	ар	r	S	L	10104	момент (N·m)
VEE077L04.0R02-03S05		3	38°	7.7	7.7	4	0.2	S05	10.0	KEYV-S05	7
VEE097L05.0R03-03S06	•	3	38°	9.7	9.7	5	0.3	S06	13.0	KEYV-S06	10
VEE117L07.0R03-03S08	•	3	38°	11.7	11.7	7	0.3	S08	16.5	KEYV-S08	15
VEE157L08.0R03-03S10		3	38°	15.7	15.3	8	0.3	S10	20.5	KEYV-S10	28
VEE197L12.0R04-03S12		3	38°	19.7	18.3	12	0.4	S12	25.5	KEYV-S12	28

JNGMEISTER Головки цилиндрические






























Переменный шаг









ар = Макс. глубина резания S = Размер присоединительной резьбы

Кат. №	Сплав	Кол-во	Угол спирали			Размер	оы (мм)	Ключ	Крутящий		
	AH725	зубьев		øDс	ød1	ар	С	S	L	10104	момент (N·m)
VEE080L05.0C30I04S05		4	38°	8	7.7	5	0.3	S05	10.0	KEYV-S05	7
VEE100L07.0C40I04S06	•	4	38°	10	9.7	7	0.4	S06	13.0	KEYV-S06	10
VEE120L09.0C50I04S08		4	38°	12	11.7	9	0.5	S08	16.5	KEYV-S08	15
VEE160L12.0C60I04S10		4	38°	16	15.3	12	0.6	S10	20.5	KEYV-S10	28
VEE200L15.0C60I04S12		4	38°	20	18.3	15	0.6	S12	25.5	KEYV-S12	28

ГЕ Головки цилиндрические












































ар = Макс. глубина резания S = Размер присоединительной резьбы

Кат. №	Сплав	Кол-во	Угол			Раз	меры (Ключ	Крутящий			
	AH725	зубьев	спирали	øDс	ød1	ар	С	S	L	α	КЛЮЧ	момент (N·m)
VEE080L05.0C25R04	4S05 •	4	45°	8	7.7	5	0.25	S05	10.0	90°	KEYV-S05	7
VEE100L07.0C30R04	4S06 •	4	45°	10	9.7	7	0.3	S06	13.0	90°	KEYV-S06	10
VEE120L09.0C35R04	4S08 •	4	45°	12	11.7	9	0.35	S08	16.5	90°	KEYV-S08	15
VEE160L12.0C40R0	5S10 •	5	45°	16	15.3	12	0.4	S10	20.5	7°	KEYV-S10	28
VEE2001 15 0C/0P0	3912	6	15°	20	12.3	15	0.4	Q12	25.5	3 °	KEVV_Q12	28

: Складские позиции/Упаковочная единица = 2 шт





10 концевые фрезы